

Index No. K 7-8

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SMC Corner common to sections 17

ON RE-ESTABLISHED ORIG. MEASURED LINE 33.98 CH. W. OF N 1/4 BTR 16 S 17

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918


Original monument 1x36" 1/4 P.W./BRASS

SMC N 517 N
1918

Original Evidence Found

Year of search _____ By _____

Monument found _____



O = Corner

Bearing Trees

| | | | | |
|----------|---------------|---------------|--|--|
| Species | <u>ROAK</u> | <u>MAPLE</u> | | |
| Diameter | <u>18"</u> | <u>9"</u> | | |
| Bearing | <u>N 66 E</u> | <u>57 6 E</u> | | |
| Distance | <u>49 LKS</u> | <u>71 LKS</u> | | |

Original Bearing Trees Found

| | | | | |
|----------|--|--|--|--|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1963 By Pete Meyer

Found GLO monument in good condition.

9" Maple 57 6 E 71 lks now stump;

Angle Point 8 S 30 13' W 2.12 chains.

Bearing Trees, Reference Objects

| | | | | |
|----------|--|--|--|--|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

Bearing Trees, Reference Objects

| | | | | |
|---------------|---------------|--|--|--|
| <u>Maple</u> | <u>Maple</u> | | | |
| <u>7"</u> | <u>6"</u> | | | |
| <u>S 35 W</u> | <u>N 31 W</u> | | | |
| <u>22.1'</u> | <u>28.3'</u> | | | |

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER 1963