


Index No. K-L 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

C-S-164 Corner common to sections 15  
AP# 1 1573, AP# 4 1604



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1918 TR 1604 AP 4  
Original monument 1X36" i.p. w/BRASS AP 1  
CAD TR 1573

Bearing Trees 5-15  
1918

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1980 By Gary Stevenson  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

<u>W. Oak</u>	<u>W. Oak</u>	<u>Ash</u>
<u>6"</u>	<u>9"</u>	<u>8"</u>
<u>N 78 W</u>	<u>S 15 W</u>	<u>N 60 E</u>
<u>8.10'</u>	<u>72.41'</u>	<u>33.55'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - GARY STEVENSON - 1981  
Doc. # 260995

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_