


Index No. 216

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
C.E. 116 Corner common to sections 15



EXISTING SURVEYS

Original Government Survey
Year surveyed 1918
Original monument 1x36" I.P.W./BRASS
CAP

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species J. PINE SPRUCE
Diameter 7" 7"
Bearing N59E N31W
Distance 206 LKS 330 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1980 By Gary Stevenson
found GLO monument in good condition.

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>Elm</u>	<u>Birch</u>	<u>J. Pine</u>	<u>W. Oak</u>
<u>9"</u>	<u>11"</u>	<u>16"</u>	<u>8"</u>
<u>N4W</u>	<u>N22E</u>	<u>N59E</u>	<u>S74W</u>
<u>98.09'</u>	<u>105.61'</u>	<u>206 LKS</u>	<u>47.89'</u>

GLO BT

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - 1981
Doc. #260997

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____