Index No. M 14

# CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

SW 1/16 Corner common to sections 15




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1918

Original monument 1X36" I.P. W/BRASS CAP

SW 1/16 S15 1918

Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | N. PINE | N. PINE | | |
| Diameter | 5" | 7" | | |
| Bearing | N43-15E | S18-15W | | |
| Distance | 51 LKS | 136 LKS | | |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 1980 By Gary STEVENSON

Location filed _____

Monument Found GLO monument in good condition.

Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | N. PINE | N. PINE | Birch | N. PINE |
| Diameter | 14" | 22" | 9" | stump |
| Bearing | N30E | N43 1/4 E | S46E | S18 1/4 W |
| Distance | 33.11' | 34.46' GLO BT | 39.32' | 90.00' |

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - GARY STEVENSON - 1981

Doc. #261001

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____