


Index No. M 16

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
SE 1/16 Corner common to sections 15



EXISTING SURVEYS

Original Government Survey
Year surveyed 1918
Original monument 1x36" 10.P. W/BASS CAP SE 1/16 S15 1918

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species TAM. TAM.
Diameter 4" 4"
Bearing S15E S34-15W
Distance 27KS 32 KS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1980 By Gary Stevenson
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species Tamarack W. OAK W Pine
Diameter 11" 12" 18"
Bearing N 75 W N 80 E S 6 E
Distance 31.50' 144.47' 249.04'

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By CERTIFICATE - GARY STEVENSON - 1981
Doc. # 261003

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____