


Index No. N 17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 22 Corner common to sections 14, 15, 22, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument POST

Species	Bearing	Trees
<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>
<u>6"</u>	<u>6"</u>	<u>7"</u>
<u>S 60W</u>	<u>N 70E</u>	<u>N 40E</u>
<u>20 LKS</u>	<u>28 LKS</u>	<u>9 LKS</u>

POPLAR
10"
S 35W
21 LKS
N 40W

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1918 By GLO

Location filed SEC. OF STATE

Monument FND 3" WOOD POST W/SPRING AND NE & NW B.T STUMPS. SET 2X36" I.P. W/BRASS CAP.

7141N R29W
515 514
522 523
1918

Evidence of Subsequent Corner Restoration

Year of search 1980 By Gary Stevenson

Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>BALSAM</u>	<u>BL. OAK</u>	
<u>6"</u>	<u>10"</u>	
<u>N 14-45E</u>	<u>N 76-15W</u>	
<u>166 LKS</u>	<u>367 LKS</u>	

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>R. OAK</u>	<u>Balsam</u>	<u>Birch</u>
<u>24"</u>	<u>20"</u>	<u>11"</u>
<u>N 76W</u>	<u>N 13E</u>	<u>S 42E</u>
<u>242.58'</u>	<u>60.12'</u>	<u>12.73'</u>
<u>GLO BT</u>		<u>35.19'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - GARY STEVENSON - 1981

Doc. # 261009

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____