


Index No. N 3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5th Coordinates: X _____ Y _____
N 1/4 19 Corner common to sections 18, 19



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species BIRCH BIRCH
Diameter 4" 4"
Bearing S 32 W N 78 W
Distance 34 LKS 13 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1917 By JOHN CURE
Location filed COUNTY BOOK "C" P. 267
Monument SET 2x4" J.M. PROPORTIONALLY

also on microfilm - roll 105 BK 56 P. 75, 77

Evidence of Subsequent Corner Restoration

Year of search 1918 By GR
FOUND 1 1/4" GALV. I.P. AT PROPORTIONAL POINT SET 1x36"
I.P. W/ BRASS CAP 1 1/4 518
519
1918

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

W. OAK W. OAK
14" 14"
N 77-15 E S 30-15 E
129 LKS 227 LKS

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Lancker
Doc. # 310037
Found 1" iron monument with brass cap.
Set 2"x24" iron monument with brass
cap 6" below surface of road. TIES:
8" Burr Oak N 24 E 53.00'; 16" Burr Oak
N 77 E 85.10'; 23" Burr Oak S 30 E 149.80'.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____