


Index No. N 4-5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
MC Corner common to sections 18, 19



EXISTING SURVEYS

Original Government Survey

Year surveyed 1918 T141 N
 Original monument 1x36" 1 1/2" W / BRASS S18
cap S19
MC

Bearing Trees 1918

Species	<u>Poplar</u>	<u>Poplar</u>	_____
Diameter	<u>12"</u>	<u>10"</u>	_____
Bearing	<u>N26W</u>	<u>S83.5W</u>	_____
Distance	<u>56 LKS</u>	<u>26 LKS</u>	_____

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By Curo
 Location filed microfilm - roll 105 BK 56 P. 77
 Monument set 2x48" I.M. mound in Sewall

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landscher
 Found 1" iron monument with brass cap.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Red Oak</u>	<u>Maple</u>	<u>Red Oak</u>	<u>Iron Pipe</u>
<u>11"</u>	<u>10"</u>	<u>19"</u>	<u>1 1/2"</u>
<u>N 40 W</u>	<u>S 50 E</u>	<u>S 8 W</u>	<u>South</u>
<u>42.75'</u>	<u>5.38'</u>	<u>50.76'</u>	<u>1.35'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landscher
Doc. # 310038