


Index No. 0 20

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 574 Coordinates: X _____ Y _____
NE 1/4 Corner common to sections 23



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1918
 Original monument 1x36" I.P. w/OAKS NE 1/4 523
CA 1918

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species W. OAK
 Diameter 10"
 Bearing S 88-30W
 Distance 5.49 CH

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____