


Index No. R 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 54H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 29 Corner common to sections 20, 21, 28, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees	Y. Pine
<u>Y. Pine</u>	<u>24"</u>	<u>Y. Pine</u>	<u>Y. Pine</u>
<u>24"</u>	<u>25"</u>	<u>24"</u>	<u>20"</u>
<u>556E</u>	<u>N33W</u>	<u>578W</u>	<u>526E</u>
<u>7 LKS</u>	<u>37 LKS</u>	<u>34 LKS</u>	<u>13 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker  
Location filed \_\_\_\_\_  
Monument Found 1" iron pipe monument.  
Set 2" x 48" iron monument with brass cap.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Species	Bearing	Trees	Reference Objects
<u>N. Pine</u>	<u>9"</u>	<u>N. Pine</u>	<u>N. Pine</u>
<u>9"</u>	<u>12"</u>	<u>14"</u>	<u>12"</u>
<u>N 87 W</u>	<u>S 23 W</u>	<u>N 70 E</u>	<u>S 19 E</u>
<u>53.23'</u>	<u>43.86'</u>	<u>87.94'</u>	<u>40.74'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1989 Certificate - David Landecker  
Doc. # 310045

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_