


Index No. V11-12

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
MC # 20 Corner common to sections 28, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>W. PINE</u>	<u>W. PINE</u>		
Diameter	<u>14"</u>	<u>8"</u>		
Bearing	<u>N 89 E</u>	<u>S 64 E</u>		
Distance	<u>77 LKS</u>	<u>90 LKS</u>		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Red Oak</u>	<u>Ash</u>	<u>Ash</u>
Diameter	<u>12"</u>	<u>5"</u>	<u>6"</u>
Bearing	<u>N 57 E</u>	<u>S 62 E</u>	<u>S 44 E</u>
Distance	<u>75.98'</u>	<u>110.55'</u>	<u>165.27'</u>

Bearing Trees, Reference Objects

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. #312152