


Index No. V R-3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____

MC# 11 Corner common to sections 30,31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>W. Pine</u>	<u>OAK</u>	
Diameter <u>24"</u>	<u>5"</u>	
Bearing <u>N16E</u>	<u>S62E</u>	
Distance <u>50 LKS</u>	<u>7 LKS.</u>	

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap, plastic base and magnet.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Trees
<u>N. Pine</u>	<u>Burr Oak</u>	<u>Burr Oak</u>
Diameter <u>19"</u>	<u>7"</u>	<u>7"</u>
Bearing <u>N38W</u>	<u>N34E</u>	<u>S89W</u>
Distance <u>43.93'</u>	<u>61.74'</u>	<u>50.53'</u>

Bearing Trees, Reference Objects

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311854

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____