


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>SEMAPLE</u>	<u>OAK</u>	<u>OAK</u>	<u>OAK</u>
Diameter	<u>6"</u>	<u>7"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>N46E</u>	<u>N48W</u>	<u>S71W</u>	<u>S78E</u>
Distance	<u>27LKS</u>	<u>13LKS</u>	<u>13LKS</u>	<u>11LKS</u>

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration
Year surveyed 1988 By David Landecker
Location filed _____
Monument Found 2" iron monument with brass cap.

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

	Bearing Trees, Reference Objects			
Species	<u>Maple</u>	<u>Burr Oak</u>	<u>Maple</u>	<u>Burr Oak</u>
Diameter	<u>7"</u>	<u>10"</u>	<u>8"</u>	<u>10"</u>
Bearing	<u>N 39 W</u>	<u>S 29 W</u>	<u>N 39 E</u>	<u>S 35 E</u>
Distance	<u>40.70'</u>	<u>62.30'</u>	<u>41.31'</u>	<u>38.35'</u>
	<u>(1965 BT)</u>	<u>(1965 BT)</u>	<u>(1965 BT)</u>	

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1965
1989 Certificate - David Landecker
Doc. # 311173

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____