


Index No. X 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 35 Corner common to sections 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>W. PINE</u>	<u>SOFT MAPLE</u>
Diameter <u>24"</u>	<u>6"</u>
Bearing <u>S80W</u>	<u>N40E</u>
Distance <u>38LKS</u>	<u>21LKS</u>

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

o = Corner

Subsequent Corner Restoration

Year surveyed 1983 By Gary Stevenson
Location filed Corner Certificate
Monument Set 2x 60" Galv. I.P. w/ 3" brass cap
at proportionate dist between NE & SE corners

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker
Found 2" iron monument with brass cap.

Bearing Trees, Reference Objects		
Species <u>N. Pine</u>	<u>Birch</u>	<u>N. Pine</u>
Diameter <u>6"</u>	<u>8"</u>	<u>20"</u>
Bearing <u>N20E</u>	<u>N52E</u>	<u>N84E</u>
Distance <u>31.94'</u>	<u>41.67'</u>	<u>41.23'</u>

Bearing Trees, Reference Objects		
<u>N. Pine</u>	<u>Red Oak</u>	<u>N. Pine</u>
<u>7"</u>	<u>5"</u>	<u>21"</u>
<u>N20E</u>	<u>N63E</u>	<u>N84E</u>
<u>31.80'</u>	<u>40.65'</u>	<u>41.10'</u>
<u>(1983 BT)</u>		<u>(1983 BT)</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - filed by USFS 1984
Doc. # 279157 dated 1983
1989 Certificate - David Landecker
Doc. # 311177

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____