


Index No. 221

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 5TH Coordinates: X SE 35 Y Corner common to sections 35, 36 W.C. 4.51 CH. WEST



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument lost W.C.

Species	Bearing	Trees
<u>W. BIRCH</u>	<u>W. BIRCH</u>	
<u>14"</u>	<u>R"</u>	
<u>N42W</u>	<u>S60E</u>	
<u>35 CKS</u>	<u>29 LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1983 By Gary Stenerson
 Location filed Corner Certificate
 Monument 2x36" Galv. l.p. w/ brass cap
206.61' N. of true SE 35

Evidence of Subsequent Corner Restoration
 Year of search 1989 By David Landecker
Set 2" x 48" iron pipe with brass cap and plastic base with magnet.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Ash</u>	<u>6"</u>	<u>N 54 W</u>	<u>40.30'</u>
<u>Maple</u>	<u>6"</u>	<u>N 15 E</u>	<u>123.04'</u>
<u>W. Pine</u>	<u>15"</u>	<u>S 38 W</u>	<u>56.51'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 312367

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____