


Index No. Z 9-10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 29 M. 57H Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

MC#16 Corner common to sections 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees	
Species	<u>Tam.</u>	<u>15H</u>
Diameter	<u>6"</u>	<u>8"</u>
Bearing	<u>N33E</u>	<u>S50W</u>
Distance	<u>18 LKS</u>	<u>18 LKS</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1989 By David Landecker  
Location filed \_\_\_\_\_  
Monument Set 3/4" x 5' aluminum rod with 3' fluted top and stamped aluminium cap.  
1/2" iron pipe plat iron West 9.00'

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>Ash</u>	<u>Ash</u>	<u>Ash</u>
Diameter	<u>20"</u>	<u>8"</u>	<u>8"</u>
Bearing	<u>N38W</u>	<u>N60E</u>	<u>N78W</u>
Distance	<u>38.87'</u>	<u>23.34'</u>	<u>41.34'</u>

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

1989 Certificate - David Landecker  
Doc. # 362158

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_