


Index No. A 14

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

w 1/16 Corner common to sections 3 AND 34-142-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
 Original monument 1x36" IP. w/1/16 cap 534
53
1917

Bearing Trees
 Species Jilane Jilane
 Diameter 4" 4"
 Bearing N 43W S 57E
 Distance 103 LKS 183 LKS

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____