


Index No. A-B 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X 452898.03 Y 195537.33
MC # 25 Corner common to sections LAND 6-141-29



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>CEDAR</u>	<u>CEAR</u>		
<u>11"</u>	<u>7"</u>		
<u>56 1/2 E</u>	<u>S13W</u>		
<u>23 LKS</u>	<u>47 LKS</u>		

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
Year surveyed 1917 By GLO
Location filed SEC. OF STATE
Monument Found wood stake & BETA B.T. STUMPS.
(S.W. BLANK OVER) SET N. 36° 11' P. W. BRASS CAP MC
51 56
R30W R29W
T141N
1917

Evidence of Subsequent Corner Restoration Found
Year of search 1/2000 By USFS, R. Main
Found GLO monument tipped, drove
8' steel post and wired to monument.

Species	Bearing	Trees, Reference Objects	Distance
<u>BIRCH</u>	<u>OAK</u>		
<u>6"</u>	<u>10"</u>		
<u>S0-30E</u>	<u>S35W</u>		
<u>43 LKS.</u>	<u>27 LKS</u>		

Bearing	Trees, Reference Objects	Distance

A, B-25

Subsequent Corner Restoration
Year surveyed 12/03 By NLS&M
Location filed USFS Cass Lake
Monument Found GLO brass cap tied to
sign post, 100' E S. of Lake. A Coff
was filed.
7" Basswood S2°E 207.15'
12" Basswood S43°W 168.60'
9 1/2" Balsam S58°W 39.25'
Steel Post South 4.6'

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared #480056
Filed at CCRO

By #16089
Date 2/12/04