


Index No. B 23

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 57H Coordinates: X _____ Y _____
C.N. 1/16 Corner common to sections 1



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1X36' / d.p. w / brass cap N 1/2 St

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species R. OAK R. OAK
Diameter 8" 8"
Bearing N 1/2 E N 67 3/4 W
Distance 69 LKS 190 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Maple R. Oak R. Oak R. Oak
Diameter 5" 8" 10" 12"
Bearing S 87 W S 75 E S 80 E N 12 E
Distance 29.33' 32.19' 27.26' 45.00'
(down)

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - WALT Curo - 1981 Doc # 26262

Remonumentation certificate prepared _____

Filed at _____ By _____ Date _____