


Index No. B 24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 1/16 Corner common to sections 1



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1917  
 Original monument 1x36" 1IP. w/ BRASS NE 1/16 S1  
CAP 1917

**Bearing Trees**

Species	<u>W. OAK</u>	<u>J. PINE</u>		
Diameter	<u>6"</u>	<u>8"</u>		
Bearing	<u>S 31 W</u>	<u>N 50 3/4 W</u>		
Distance	<u>228 LKS</u>	<u>249 LKS</u>		

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed 1981 By Walter Curo  
 Location filed \_\_\_\_\_  
 Monument Found GLO monument in good condition.

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	<u>R. OAK</u>	<u>W. OAK</u>	<u>N. PINE</u>	<u>W. OAK</u>
Diameter	<u>8"</u>	<u>5"</u>	<u>18"</u>	<u>14"</u>
Bearing	<u>N 2 W</u>	<u>N 50 E</u>	<u>S 30 E</u>	<u>S 31 W</u>
Distance	<u>14.59'</u>	<u>16.80'</u>	<u>34.04'</u>	<u>150.50'</u>
				<u>(1917 BT)</u>

**Bearing Trees, Reference Objects**

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - WALTER CURO - 1981 Doc. # 262620