


Index No. C12

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C. E. 116 Corner common to sections 4



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1917  
Original monument 1x36" h.p. w/BRASS CAP E 1/16  
54  
1917

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species ROAK ROAK  
Diameter 14" 16"  
Bearing N60 1/2 E S54 1/4 W  
Distance 73 LKS 81 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1963 By Pete Meyer  
Location filed \_\_\_\_\_  
Monument Found GIO monument in good condition; 14" R. Oak N60 1/2 E 48.18' now stump; 16" R. Oak S54 1/2 W 53.46' now 24"

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
Species Oak Oak Oak  
Diameter 5" 9" 7"  
Bearing S13E N76W N4W  
Distance 19.50' 52.00' 65.70'

Bearing Trees, Reference Objects  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1963