


Index No. C 22

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C. W. 11/16 Corner common to sections 1



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument 1x36" 11/16 W BRASS CAP w/116 51 1917 C

Bearing Trees

Species M. Pine W. Oak  
Diameter 10" 6"  
Bearing N 87 1/2 E S 35 1/2 W  
Distance 490 LKS 41 LKS

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species B. Oak B. Oak B. Oak  
Diameter 6" 8" 7"  
Bearing N 80 W N 80 E S 10 W  
Distance 18.88' 17.54' 16.67'

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - WACT Curo - 1981 Doc # 262607

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_