


Index No. C 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 S Corner common to sections 4, 5



o = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>1/4 PINE</u>	<u>1/4 PINE</u>	Bearing Trees
Diameter	<u>8"</u>	<u>10"</u>	
Bearing	<u>N75E</u>	<u>N114E</u>	
Distance	<u>23 LKS</u>	<u>76 LKS</u>	

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1911 By A.W. Moulster
Location filed COUNTY SURVEY RECORD BOOK 'A' P 480-482
Monument FIND OLD GOVT BT: 8" 1/4 PINE N75E
15.18' SET SMALL POST
1975, MILO STEFAN, PLAT OF SURVEY 'E-73', IN 1975, R.F. SCHNEIDER
FOUND THE GENERAL LAND OFFICE RESURVEY MARKER OF 1911

Evidence of Subsequent Corner Restoration

Year of search 1917 By GLO
SET 1 X 3/8" IR. W/ BRASS CAP PROPORTIONALLY
114
55/58
1917

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>PINE</u>	<u>JAM.</u>	_____	_____
<u>17"</u>	<u>6"</u>	_____	_____
<u>N 80E</u>	<u>S 62 1/2 W</u>	_____	_____
<u>358 LKS</u>	<u>190 LKS</u>	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - PLAT OF SURVEY
R.F. SCHNEIDER 1975

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____