


Index No. D 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 57H Coordinates: X 452803.68 Y 191859.34
S116 Corner common to sections 1 AND 6-141-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917 S116
Original monument 1x36" I.P.W/BASS 51/56
CAP 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species OAK OAK _____
Diameter 12" 12" _____
Bearing S37E S39 3/4 W _____
Distance 56 LKS 242 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search 9/99 By USFS, P. Main
Found monument 11' W. of FR #3744.

Bearing Trees, Reference Objects

Species Maple R. Oak Maple _____
Diameter 5" 8" 7" _____
Bearing S61°16'W S27°34'W N56°58'E _____
Distance 41.38' 58.31' 50.97' _____

Bearing Trees, Reference Objects

D-25

Subsequent Corner Restoration

Year surveyed 9/03 By NLSEM
Location filed USFS Cass Lake
Monument Found GLO monument, 11' W. of Rogers Point Road and list the following witnesses. A Co of L was filed.
9" Maple N56°W 15.13'
7" Twin Maple S24°E 81.63'
11" Maple N54°E 50.64'
Steel Post North 2.68'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - WALT CURO - 1981
Doc. # 262647

Remuneration certificate prepared #480059
Filed at CCRO

By #16089
Date 2/12/04