


Index No. DE 2

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S-Sw 1/64 Corner common to sections 6  
AP# 3 1324



EXISTING SURVEYS

**Original Government Survey**  
Year surveyed 1917  
Original monument 1x36" i.p.w. Brass TR 1303 TR 1324 AP 3  
Cap 56  
1917

**Original Evidence Found**  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Bearing Trees**  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Original Bearing Trees Found**  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**  
Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

**Bearing Trees, Reference Objects**

**Subsequent Corner Restoration**  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_