


Index No. E 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 10 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1873  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species BALSAM SPRUCE  
 Diameter 8" 12"  
 Bearing S 42 1/2 W N 57 1/2 W  
 Distance 29 LKS 18 LKS

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1917 By GLO  
 Location filed SEC. OF STATE  
 Monument SET 1436" I.P. w/ BRASS CAP PROPORTIONATE  
114 53  
510  
1917

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 Species CEDAR BALSAM  
 Diameter 18" 15"  
 Bearing S 44 W N 42 1/2 W  
 Distance 44 LKS 4 LKS

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_