


T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 1, 2, 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
 Original monument POST

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Species	Bearing Trees			
	Y. PINE	R. OAK	Y. PINE	Y. PINE
Diameter	10"	6"	10"	18"
Bearing	S15W	S57E	N62E	N57 1/2 W
Distance	130 LKS	100 LKS	75 LKS	192 LKS

Original Bearing Trees Found

Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration

Year surveyed 1917 By GLC
 Location filed SEC. OF STATE
 Monument FIND OLD WOOD STAKE AND ALL 4 CORNERS
B.T. STUMPS. T141N R30W
S2 | S1
S11 | S12

Evidence of Subsequent Corner Restoration

Year of search 1983 By USFS
 Find evidence of all 1917 B.T.S and one tree from 1921 certificate set
2' x 24" galv. 11p. w/ brass cap

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects		
	R. OAK	J. PINE	Y. PINE
Diameter	10"	8"	24"
Bearing	N25 3/4 E	S66 1/4 E	N57W
Distance	235 LKS	280 LKS	198 LKS

Bearing Trees, Reference Objects

W. oak	W. oak	R. oak	W. oak	W. oak	W. oak	N. Pine
8"	14"	11"	8"	8"	26"	
S9°W	S30°E	N37E	N28E	N3°W	N57W	
93.55'	94.35'	59.62'	77.55'	58.15'	130.20'	

E-21

Subsequent Corner Restoration

Year surveyed 8/01 By CCSO
 Location filed file # 2001.037
 Monument Found Brass cap, down 0.1', 11'E
N. of & Hwy #200. 1983 witnesses to
North are mostly dead, add following:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BUTLER SMITH - HWY ENGINEER - 1921
Certificate - Ken Whitthorn USFS - 1986
DOC # 287749

14" N. Pine N 4° E, 40.35' to dbl. hd. nail

Jul 2002 T. Freeman
Cert. of Sky. shows mon. found.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____