


Index No. E-F 22

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5th Coordinates: X _____ Y _____

AP# 2 Corner common to sections 12
TR 1320 (N-NW 1/4)



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1x36' 1.1/2" W BRAS TR 1316 TR 1320
CRP S 1/2

Bearing Trees 1917
Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo
Location filed _____
Monument Found GLO monument in good condition.

Bearing Trees, Reference Objects
Species W. Oak W. Oak W. Oak
Diameter 5" 5" 5"
Bearing N37°58'W N87°20'E 55°44'E
Distance 12.44' 11.60' 14.10'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - WALTER CURO - 1981
Doc. # 262628

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____