


Index No. F-6 20

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

AP# 2 Corner common to sections 11  
TR 1223, AP# 3 1226 (S-NE 1/64)



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument 1x36" 1 1/2" w/BRASS TR 1226  
CAP 1353 AP 3  
AP 2  
Bearing Trees 1917  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1981 By Walter Curo  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species Maple Maple w. Oak  
Diameter 5" 10" 5"  
Bearing N35E S58E S58W  
Distance 9.48' 36.36' 29.56'

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - WALTER CURO - 1981  
Doc. # 262638

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_