


Index No. G 16

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
 C.E.  $\frac{1}{16}$  Corner common to sections 10



○ = Corner

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1917  
 Original monument 1x36" IR. W/BRASS  
CAP

**Bearing Trees**  
 Species J. PINE J. PINE  
 Diameter 12" 16"  
 Bearing N39E S20W  
 Distance 17 LKS 17 LKS

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1968 By William Okerman  
 Location filed \_\_\_\_\_  
 Monument Found GLO monument in good condition.

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>Oak</u>	<u>12"</u>	<u>S28W</u>	<u>10.35'</u>
<u>Oak</u>	<u>9"</u>	<u>N42W</u>	<u>25.80'</u>
<u>Oak</u>	<u>9"</u>	<u>N44E</u>	<u>25.10'</u>
<u>Cedar FENCE Post</u>	<u>10"</u>	<u>South</u>	<u>0.6'</u>

**Bearing Trees, Reference Objects**  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

---



---



---



---



---



---



---



---



---



---



---

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1968  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_