


T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 11 Corner common to sections 11, 12



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species PINE STUB OAK STUB
Diameter 24" 12"
Bearing S 32 1/2 W N 53 1/2 E
Distance 104 LKS 146 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
Location filed SEC. OF STATE
Monument SET 1x36" I.P. w/ BRASS CAP PROPORTIONALLY
5 11/14
5 11/512
1917

Evidence of Subsequent Corner Restoration

Year of search 1962 By PETE MEYER
Found GLO monument in good condition;
5" R. OAK S 13 1/4 W 23.76' now 7"

Bearing Trees, Reference Objects

Species R. OAK R. OAK
Diameter 6" 5"
Bearing N 32 1/4 E S 13 1/4 W
Distance 47 LKS 36 LKS

Bearing Trees, Reference Objects

OAK OAK OAK
8" 9" 13"
S 36 W S 41 E N 35 1/2 W
29.70' 28.50' 83.50'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962