


Index No. G 23-24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____

C-W-E 1/64 Corner common to sections 12
AP# 4 1694, AP# 3 1695



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917 By TR1694 / TR1695
Original monument 1x36" I.D.W/BRASS AP 4 | AP 3
CAD SIR

Bearing Trees 1917
Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1968 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species R. Pine Cedar Post
Diameter 20" 4x4x60"
Bearing N60W East
Distance 72.8' 2.8'

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1968

Remonumentation certificate prepared _____

Filed at _____

By _____

Date _____