


Index No. K18

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
NW 116 Corner common to sections 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1836' 1/4 W/800'S NW 116 514
cap 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

O = Corner

Species	Bearing	Trees
<u>Poplar</u>	<u>Poplar</u>	
<u>7"</u>	<u>8"</u>	
<u>N41 3/4 E</u>	<u>546 W</u>	
<u>32 LKS</u>	<u>12 LKS</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1968 By William Okerman
Location filed _____
Monument Found GLO monument in good
condition

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>N. Pine</u>	<u>W. Pine</u>	
<u>13"</u>	<u>13"</u>	
<u>N37 E</u>	<u>N 70 E</u>	
<u>43.75'</u>	<u>55.60'</u>	

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Bill Okerman - 1968 - recorded 1971

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____