


Index No. L 15

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C/4 Corner common to sections 15



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument 1x36' 1/2 P. W/BRASS CAP C/4 S/5 1917

Bearing Trees  
Species N. PINE J. PINE  
Diameter 8" 10"  
Bearing S62 1/4 E N60 1/2 W  
Distance 368 LKS 245 LKS

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition; 10" J. Pine N(68 1/2 W) 161.70' now 13"

Bearing Trees, Reference Objects

Species J. Pine Oak  
Diameter 12" 6"  
Bearing N 7 1/2 W N 53 E  
Distance 34.20' 26.75'

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_