


Index No. L 116

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
C.E. 116 Corner common to sections 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917
Original monument 1x36" 1/4 W BRASS CAP E 116 C 515 C 1917

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

| | | | |
|----------|-------------------|------------------|-------|
| Species | <u>R. OAK</u> | <u>POPULAR</u> | _____ |
| Diameter | <u>6"</u> | <u>14"</u> | _____ |
| Bearing | <u>S 32 1/4 E</u> | <u>S 4 1/4 W</u> | _____ |
| Distance | <u>170 LKS</u> | <u>184 LKS</u> | _____ |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1962 By PETE MEYER
Location filed _____
Monument Found GLO monument in good condition; 6" Red Oak S 32 1/4 E 112.20' now 13"; 14" Poplar S 4 1/4 W 121.44' now stump hole.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | | |
|----------|----------------|-------------------|-------|
| Species | <u>J. Pine</u> | <u>OAK</u> | _____ |
| Diameter | <u>9"</u> | <u>13"</u> | _____ |
| Bearing | <u>N 85 E</u> | <u>S 32 1/4 E</u> | _____ |
| Distance | <u>67.4'</u> | <u>112.2'</u> | _____ |

Bearing Trees, Reference Objects

| | | | |
|-------|-------|-------|-------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____