


Index No. L9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 17 Corner common to sections 16, 17



EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1873</u>	Year of search _____ By _____
Original monument <u>POST</u>	Monument found _____

Bearing Trees		Original Bearing Trees Found	
Species <u>CEDAR</u>	<u>CEDAR</u>	Species _____	_____
Diameter <u>10"</u>	<u>10"</u>	Diameter _____	_____
Bearing <u>S 51 E</u>	<u>N 22 W</u>	Bearing _____	_____
Distance <u>20 LKS</u>	<u>12 LKS</u>	Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1917 By GLO
 Location filed SECC OF STATE
 Monument SET 1X36" I.P. w/ BRASS CAP PROPORTIONALLY. 14
S 17 1/2 E
1917

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species CEDAR CEDAR

Diameter 8" 8"

Bearing S 49 3/4 E S 50 3/4 W

Distance 195 LKS 79 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____