


T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C.C. on \_\_\_\_\_ Corner common to sections \_\_\_\_\_  
S. BARY. INDIAN RES.



EXISTING SURVEYS

Original Government Survey

Year surveyed 1917  
Original monument N36° 1/2 W / BRASS  
CR

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

		Bearing Trees		
Species	<u>N. PINE</u>	<u>J. PINE</u>		
Diameter	<u>8"</u>	<u>4"</u>		
Bearing	<u>S6 1/2 E</u>	<u>N 80 1/4 W</u>		
Distance	<u>254 LKS</u>	<u>148 LKS</u>		

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1963 By PETE MEYER  
Location filed \_\_\_\_\_  
Monument Found GLO monument in good condition; 8" N. PINE S6 1/2 E 167' now 12" stub; 4" J. PINE N 80 1/4 W 97.68' now 13"

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>W. PINE</u>		
Diameter	<u>12"</u>	<u>7"</u>		
Bearing	<u>S 81 W</u>	<u>S 30 E</u>		
Distance	<u>72.45'</u>	<u>71.8'</u>		

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Pete Meyer - 1963