


Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 24 Corner common to sections 24 AND 19-141-29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument AST

Species	Bearing	Trees
<u>W. PINE</u>	<u>W. PINE</u>	
<u>6"</u>	<u>10"</u>	
<u>N 31 1/2 W</u>	<u>N 64 1/2 E</u>	
<u>44 LKS</u>	<u>39 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1912 By John C. Leo

Location filed COUNTY SURVEY RECORD BOOK "A" P. 499

Monument FIND OLD GOVT BT STUMP 10" W. PINE N 64 1/2 E 25.74', ROOTS OF 6" W. PINE N 31 1/2 W 29.04' SET 3x3x36" OAK STAKE

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker

Set 2" x 48" iron pipe with brass cap.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPULAR</u>	<u>3"</u>	<u>N 63 E</u>	<u>26.50'</u>
<u>POPULAR</u>	<u>3"</u>	<u>S 60 E</u>	<u>20'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Burr OAK</u>	<u>10"</u>	<u>N 58 W</u>	<u>55.53'</u>
<u>N. PINE</u>	<u>6"</u>	<u>S 86 E</u>	<u>20.86'</u>
<u>Burr OAK</u>	<u>10"</u>	<u>S 40 W</u>	<u>16.85'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1989 Certificate - David Landecker

Doc. # 311063

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____