


Index No. R3

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
N1/4 30 Corner common to sections 19, 30



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1873
 Original monument Post

| Species | Bearing | Trees |
|----------------|----------------|-------|
| <u>TAM.</u> | <u>TAM.</u> | |
| <u>6"</u> | <u>4"</u> | |
| <u>N41W</u> | <u>S9W</u> | |
| <u>139 LKS</u> | <u>154 LKS</u> | |

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| | | | |
| | | | |
| | | | |
| | | | |

Subsequent Corner Restoration
 Year surveyed 1922 By E. B. HERST
 Location filed COUNTY RESURVEY E-38"
 Monument IRON MONUMENT
1922, E. B. HERST, BOOK E P. 468 F.N.O. CORNER, P. 469 SET
2x48" I.M.

Evidence of Subsequent Corner Restoration
 Year of search 1990 By Laverne Leuelling
 Found GLO monument deteriorated. Set
brass capped monument.

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| | | | |
| | | | |
| | | | |
| | | | |

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|------------|-----------|---------------|---------------|
| <u>OAK</u> | <u>5"</u> | <u>N 55 W</u> | <u>66.84'</u> |
| <u>OAK</u> | <u>6"</u> | <u>N 3 W</u> | <u>82.64'</u> |
| <u>OAK</u> | <u>9"</u> | <u>S 85 E</u> | <u>73.58'</u> |

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1964
1989 Certificate - David Landecker
Doc. # 309846
1991 Certificate - Laverne Leuelling
Doc. # 326705

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____