


Index No. R 9

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 29 Corner common to sections 20, 21, 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>R. OAK</u>	<u>R. OAK</u>	<u>W. PINE</u>	<u>MAPLE</u>
Diameter	<u>13"</u>	<u>11"</u>	<u>9"</u>	<u>8"</u>
Bearing	<u>N46 1/2 W</u>	<u>N20 E</u>	<u>S71 1/2 E</u>	<u>S78 1/2 W</u>
Distance	<u>56 LKS</u>	<u>61 LKS</u>	<u>34 LKS</u>	<u>49 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Set 2" x 48" iron pipe with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects			
	<u>Ash</u>	<u>Birch</u>	<u>Burr Oak</u>	<u>Red Oak</u>
Diameter	<u>5"</u>	<u>8"</u>	<u>6"</u>	<u>5"</u>
Bearing	<u>N65W</u>	<u>S50W</u>	<u>N89E</u>	<u>S29E</u>
Distance	<u>71.27'</u>	<u>4.24'</u>	<u>19.19'</u>	<u>29.57'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
1989 Certificate - David Landecker
Doc. # 311065

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____