


Index No. V 17

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 34 Corner common to sections 26, 27, 34, 35



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Types	Distance
<u>Y. PINE</u>	<u>Y. PINE</u>	<u>Y. PINE</u>	<u>Y. PINE</u>
Diameter <u>13"</u>	<u>14"</u>	<u>9"</u>	<u>16"</u>
Bearing <u>S45E</u>	<u>N70E</u>	<u>N 81 1/2 W</u>	<u>S41W</u>
Distance <u>46 LKS</u>	<u>49 LKS</u>	<u>44 LKS</u>	<u>98 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Found 2" iron monument with brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Oak</u>	<u>Oak</u>	<u>Burr Oak</u>	<u>Birch</u>
<u>12"</u>	<u>14"</u>	<u>9"</u>	<u>8"</u>
<u>N38W</u>	<u>S86W</u>	<u>N26E</u>	<u>S14E</u>
<u>45.47'</u>	<u>47.58'</u>	<u>37.32'</u>	<u>65.25'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1964
1989 Certificate - David Landecker
Doc. # 310877

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____