


Index No. V 21

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>BIRCH</u>	<u>MAPLE</u>	<u>POPULAR</u>	<u>W. PINE</u>
Diameter <u>10"</u>	<u>8"</u>	<u>5"</u>	<u>14"</u>
Bearing <u>S 65 1/2 E</u>	<u>S 5 W</u>	<u>N 20 E</u>	<u>N 38 W</u>
Distance <u>59 LKS</u>	<u>34 LKS</u>	<u>48 LKS</u>	<u>65 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1988 By David Landecker
Location filed _____
Monument Found concrete monument with Brass cap.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Species	Bearing	Trees	Reference Objects
<u>Red Oak</u>	<u>Burr Oak</u>	<u>Burr Oak</u>	<u>Red Oak</u>
Diameter <u>6"</u>	<u>5"</u>	<u>6"</u>	<u>6"</u>
Bearing <u>N 70 W</u>	<u>N 55 E</u>	<u>N 73 E</u>	<u>S 15 E</u>
Distance <u>69.32'</u>	<u>55.57'</u>	<u>33.72'</u>	<u>33.93'</u>
	<u>(1965 BT)</u>		<u>(1965 BT)</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL CLEEMAN - 1964
1989 Certificate - David Landecker
Doc. # 310680

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____