


T. 141 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 31 Corner common to sections 30, 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees	
	TAM.	TAM.
Diameter	<u>10"</u>	<u>12"</u>
Bearing	<u>576E</u>	<u>N64E</u>
Distance	<u>60WS</u>	<u>76LWS</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed 1972 By E.B. Hest
Location filed COUNTY RESURVEY 'E-38'
Monument IRON MONUMENT - GOUT BITS.
1920, E.B. HEST, BOOK 'C' P. 465 FIVE CORNER (P. 468 I.M.)

Evidence of Subsequent Corner Restoration

Year of search 1988 By David Landecker
Set 2" x 48" iron pipe with brass cap
over 14' of steel sign posts.
8' steel sign post N 45 E 8.25'; 8'
steel sign post South 8.40'; 8" steel
sign post N 81 W 5.94'.

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Bearing Trees, Reference Objects

Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - LOTHROP
R.E. TAFT. 1895
PLAT - BROWN'S TEN MILE SHORES
R.F. SCHNEIDER 1969
1989 Certificate - David Landecker
Doc. # 312369
1999 - Landecker + Assoc.
Cert. of Survey indicates an I.M.
found + in place.
Feb. 2002 Benson & Associates 19700