


Index No. V5

CASS COUNTY LAND CORNER RECORD

T. 141 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 31 Corner common to sections 29, 30, 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing Trees			
	<u>YIPINE</u>	<u>YIPINE</u>	<u>OAK</u>	<u>POPLAR</u>
Diameter	<u>13"</u>	<u>16"</u>	<u>10"</u>	<u>14"</u>
Bearing	<u>S43W</u>	<u>N51 1/2 W</u>	<u>S30E</u>	<u>N31E</u>
Distance	<u>29LKS</u>	<u>32LKS</u>	<u>54LKS</u>	<u>99LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1922 By E. B. HORST  
Location filed COUNTY RESURVEY "E-38"  
Monument IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1988 By DAVID LANDECKER  
Set 10' aluminum rod with aluminum cap.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Burr OAK</u>	<u>19"</u>	<u>N 53 W</u>	<u>127.30'</u>
<u>W. Pine</u>	<u>24"</u>	<u>N 38 W</u>	<u>110.45'</u>
<u>N. Pine</u>	<u>17"</u>	<u>S 68 W</u>	<u>152.50'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
1989 Certificate - David Landecker  
Doc. # 309848

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_