Index No. A 10

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

W 1/16 Corner common to sections 4 AND 33 - 142-31



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species			
Diameter			
Bearing			
Distance			

Original Bearing Trees Found

Species			
Diameter			
Bearing			
Distance			

Subsequent Corner Restoration

Year surveyed 1962 By Pete Meyer

Location filed _____

Monument Found 2" capped iron pipe. Set 2"x5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

Species	Oak	Oak		
Diameter	6"	5"		
Bearing	N48W	S27W		
Distance	22.70'	15.5'		

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____