


T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
MC # 25 Corner common to sections 4 AND 33-142-31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species BIRCH BIRCH _____
Diameter 3" 3" _____
Bearing N39W S70W _____
Distance 29 LKS 25 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1925 By JOHN GREENE
Location filed COUNTY RESURVEY "E-51"
Monument IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Certificate - Gary Stevenson - 1985
Doc. # 284231
M.C. in lake, Feb 1925 l.p. laying flat
set 2x36" l.p. w/ brass cap on section
line
12" w. oak N85w 21.48'
5" w. oak S24W 13.79'

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____