


Index No. AR3-24

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____
ML# 38 Corner common to sections 1 AND 36-142-31



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species SPRUCE BIRCH
Diameter 5" 5"
Bearing N30-30E S5-30E
Distance 9 LKS 4 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search 1950 By HAROLD CICO
COUNTY BOOK'D " R408 FND BRASS CAP. MONUMENT

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
PLAT - BAYWOOD
R.F. SCHNEIDER 1971

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____