


Index No. B 25

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/16 Corner common to sections 1 AND 6-141-30



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1917  
Original monument 1x36" l.p. w/ BRASS CAP

N 1/16  
S 11 56  
1917

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. OAK PINE  
Diameter 4" 14"  
Bearing S 25 1/2 E N 5 1/2 W  
Distance 107 LKS 197 LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
Year of search 1984 By Freeman & USFS  
C. Krause, G. Brauma, Jeff Allison  
Find 1x30" l.p. (GLO ran w/ top 6" gone)  
down 1' in & N-S road - bottom of l.p. in  
rock mound - also GLO pine stump NW 131'  
Set 2" Brass cap l.p. over GLO IRON

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
W. oak N. Pine N. Pine  
12" 7" 9"  
N 21 E N 53 E S 26 E  
80.45' 73.30' 82.98'

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_