


Index No. C 21-22

CASS COUNTY LAND CORNER RECORD

T. 141 R. 31 M. 5TH Coordinates: X _____ Y _____

C - W - W 1/64 Corner common to sections 1

SE Cor. TR 1225, SW Cor. TR 1226



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1917 Original monument 1x36" Lip. W/BRASS

AP4 AP3
TR 1225 TR 1226

Bearing Trees

Species _____ Diameter _____ Bearing _____ Distance _____

CAP 51
TR 1595
1917

Original Evidence Found

Year of search _____ By _____ Monument found _____

Original Bearing Trees Found

Species _____ Diameter _____ Bearing _____ Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____ Location filed _____ Monument _____

Bearing Trees, Reference Objects

Species _____ Diameter _____ Bearing _____ Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____ Location filed _____ Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Plat - Belle Terre - R.F. Schneider 1919

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____