


Index No. C-D 9

CASS COUNTY LAND CORNER RECORD

T. 741 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC Corner common to sections 4,5



EXISTING SURVEYS

Original Government Survey  
Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1962 By Pete Meyer  
Location filed \_\_\_\_\_  
Monument Found 2"x20" iron pipe. Set 2"x5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Evidence of Subsequent Corner Restoration  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects  
Species Red Pine Oak  
Diameter 18" 5"  
Bearing S14W S89E  
Distance 42.8' 17.0'

Bearing Trees, Reference Objects  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE PETE MEYER - 1962  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_